

# Submission: **FIN 2**

Reporting committee: **ITC**

---

## **ASYMMETRIC SPINNAKER AND CODE 0 TREATMENT**

### **PROPOSAL**

Revise the VPP to treat asymmetric spinnakers and Code 0's more fairly. The jump at 75% should be removed and the coefficients of an asymmetric spinnaker at tight angles should be checked.

### **RATIONALE**

Many boats have a "fake" Code 0 just at 75% made from laminate. This seems to have very little effect on the rating for boats having symmetric spinnakers, but still makes them clearly faster in conditions where boats have difficulties carrying a spinnaker. The rating jump to 74.9% Code 0 makes it much less used.